

TP170516 RELAY MOUNTING BRACKET

APPARATUS AFFECTED: 1A and 2A Sender Cabinet — DATASPEED.

OBJECT: To facilitate wiring by providing additional clearance for routing of wires to the relays.

CHANGE: The relay mounting surface on the TP170516 bracket has been changed from a length of 2-3/16 inches to 2-7/16 inches. The formed bracket mounting sections have been changed from a length of 1/2 inch to 3/8 inch.

Refer to Teletype Bulletin 1176B, page 4-9, change 2.

IDENTIFICATION: See "CHANGE".

INTERCHANGEABILITY: New and old style TP170516 brackets are interchangeable.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect.

W.E.CO. STOCK OF OLD STYLE PARTS: Old style parts may be furnished.

APPLICATION TO APPARATUS IN THE FIELD: Old style parts giving satisfactory service need not be replaced.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: Units may be equipped with new or old style parts.

AVAILABILITY: New style relay mounting brackets are now available.