

DATA SET 603D INSTALLATION INSTRUCTIONS

1. GENERAL

1.01 This section contains instructions for connecting and installing the Data Set 603D. This section does not include specific installation methods or operating information for the associated business machine and related equipment.

1.02 The set must be located within range of the interface connector cord attached to the business machine and convenient to a standard telephone set.

2. SPECIAL TOOLS

2.01 No special tools are required for the installation of a Data Set 603D.

3. CONNECTIONS

3.01 Uncover the interface connector jack J1 by moving the hinged protective cover as illustrated in Fig. 1. Insert a probe and release




Fig. 1 — Data Set 603D, Rear View

SECTION 596-014-200

the battery cover latch. Check that the battery complement is complete and properly installed. Close the battery compartment cover and connect the business machine connector cord plug to the interface jack.

3.02 Fig. 2 illustrates the typical connection required between the data set and standard telephone equipment.



Fig. 2 — Typical Connection Between Data Set 603D and Standard Telephone Equipment