

**T1 CARRIER
SYSTEM REQUIREMENTS
AND
REPEATER BAY EQUIPMENT
EQUIPMENT DESIGN REQUIREMENTS
COMMON SYSTEMS**

1. GENERAL

(b) Under Subdivisions of Equipment and Detailed Index, J98710S—removed.

1.001 This addendum supplements Section 801-523-150, Issue 3.

Remove: 1.60 and Fig. 36.

1.002 The addendum is issued to remove all reference to J98710S, which has been canceled.

Under Subdivisions of Equipment and Detailed Index

1.003 The following changes apply to Part 1 of the section:

(a) 1.60—Removed

Remove: J98710S

EQUIPMENT CODE	RATING	TITLE	EQUIPMENT DRAWING	CIRCUIT DRAWING	WEIGHT OF UNIT IN POUNDS
J98710S	AT&TCo Std	Span Fault Locator	J98710S-()	SD-3C096-01	20

2. SUPPLEMENTARY INFORMATION

Under J98710S, List 1

The following changes apply to Part 2 of the section:

Remove:

Remove:

Floor Plan Data—Section 3.3, Sheet 41 (Bays per ED-97162-51)

J98710S—AT&TCo Standard—Span Fault Locator Equipment—J98710S-()

4. EQUIPMENT

List 1—Assembly, wiring and equipment required for one span fault locator per SD-3C096-01.

The following changes apply to Part 4 of the section:

(a) J98710S—removed

Bell Telephone Laboratories, Incorporated

Dept 4321