

**ORIGINATING MARKER FRAME
EQUIPMENT DESIGN REQUIREMENTS
NO. 1 CROSSBAR SYSTEM**

1. GENERAL

1.001 This addendum supplements Section 816-350-150, Issue 12

1.002 This addendum is issued to provide information for offices which charge for directory assistance calls in accordance with SD-25016-01, Issue 115B.

4. EQUIPMENT

The following change applies to Part 4 of the section:

- (a) J28751A, Lists 59, 60, 61, 62, and 63—added

Under J28751A

Add:

List 59—Equipment and wiring per SD-25016-01, option QI required in addition to list 3 in offices that charge for directory assistance calls and require the generation of message billing index 16.

List 60—Equipment and wiring per SD-25016-01, option QN required in addition to list 3 and 59 for 555-1212 calls or in addition to list 3 in

offices that charge for directory assistance calls, 555-1212, that are completed on a straightforward basis.

List 61—Equipment and wiring per SD-25016-01, option QM required in addition to list 3 and 59 for 411 calls or in addition to list 3 in offices which charge for directory assistance calls, 411, that are completed on a straightforward basis.

List 62—Equipment and wiring per SD-25016-01, option QP required in addition to list 1 in ANI offices which charge for directory assistance calls when the second 2-party test is required by the subscriber sender where the marker grounds the CL3 lead or in addition to list 3 in offices that charge for directory assistance calls that are completed on a straightforward basis.

List 63—Equipment and wiring per SD-25016-01 option QK required in addition to list 1 in ANI offices that charge for directory assistance calls, 555-1212, which are completed on a straightforward basis.

Bell Telephone Laboratories, Incorporated

Dept 5245

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement

Printed in U.S.A.