



L		A-	
ISSUE			
USED ON		DWG.	
● DENOTES MANUFACTURE DISCONTINUED	■ DENOTES MANUFACTURE LIMITED		
300 & 325 TYPE TEL. SETS INNER DOOR ASSEMBLY			
SCALE			
DRAWN	APPROVED		
CHECKED			
WESTERN ELECTRIC CO. INC. ENGINEER OF MANUFACTURE			
LA-			
L			

ISSUE 1	12-11-50
TWO .138-32 SCREWS, & P 294111 WERE NOT SPEC., .112-40 SCREW WAS RM 612989. 1/4 IN. CELL. ACETATE CLIP WAS RM 601828. SEC. A-A WAS NOT SHOWN. ".138" 32 --- LOCK WASHER" & "MOUNTED WITH --- SCREWS - 3/8" LG" WERE NOT SPEC.	
D.M.H.	
ISSUE 2	7-31-53
IN TITLE "INNER DOOR ASSEMBLY" WAS "B.S.P. SEC. D 451.502"	
W.R.W.	E.W.S. M.E.L.
ISSUE 3	9-3-53
ON DWG. WORD "STAKE" AND FOR LOOP TYPE CLIP "OR NYLON" WERE "NOT SPEC." P-337066 WAS "FIG. 6 OR P-337066."	
R.H.D.	V.S.K. E.M.
ISS. 4	12-29-57
P-181315 B.H.M. SCREW WITH P-243248 LOCK WASHER WAS .138"-32 R.H. ST. 376. M. SCREW 1/2" LG. WITH P-221613 LOCKWASHER.	
FEB	F.O.B. C.L.L.
ISS: 5	9-24-58
APPL'S	
CH.	
DR.	C.A. SCHRUMBA ENG. J.M. MAYER
BELL TELEPHONE LABORATORIES, INC. NEW YORK	
BL-220383	
LA-	

LA-