

**BELL SYSTEM PRACTICES**  
**Station Installation and Maintenance**

**ADDENDUM C32.560**  
**Issue 1, April, 1956**  
**AT&T Co Standard**

## **TELEPHONE SETS**

### **554, 556, AND 558 TYPES**

### **INSTALLATION AND MAINTENANCE**

#### **1. GENERAL**

1.01 This addendum supplements Section C32.560, Issue 1. It is issued to add information on the C4A ringer used in these telephone sets.

#### **3. MAINTENANCE**

3.01 Change to read: All components of these sets, except the early model C4A ringers, are interchangeable with the 500-type telephone sets. The frames on all C4A ringers manufactured after January 15, 1955 have been changed in design so that they will not interfere with the free movement of the volume-adjusting arm as did the earlier model. The maintenance of these components is covered in other sections of the C practices.

**ADDENDUM**  
**C32.560**

Page 1  
1 Page

**TELEPHONE SETS**  
**554, 556, AND 558 TYPES**  
**INSTALLATION AND MAINTENANCE**