

BELL SYSTEM PRACTICES
Station Installation
and Maintenance

ADDENDUM C42.138
ADDENDUM C64.227
Issue A, 2-16-50
N.Y.TEL.CO.(All Areas)

55,155,166 AND 191 TYPE COIN COLLECTORS
MULTI-SLOT, PREPAYMENT TESTS AND ADJUSTMENTS

This addendum modifies Section C42.138 - C64.227
Issue A as follows:

1. GENERAL

Paragraph 1.01 of the section is replaced by the
following paragraph:

1.01 This section provides maintenance procedures for coin
collectors, converted for ten cent operation, which
are equipped with stainless steel coin chutes and P-339881
cut-over clips.

2. TESTS

In order to insure that the P-339881 cut-over clip
will be in place after testing is completed, make the tests
for 10¢ initial calling rate first and the tests for 5¢
initial calling rate last.

ADDENDUM
C42.138
C64.227 CN. COL.
Page 1 TESTS
1 Page AND ADJ.