


ISSUE 1 5-2-38
 REDRAWN FROM ISSUE 1 DUE TO MINOR CHANGES
 R.I.F.
 ISSUE 2 2-10-39
 REDRAWN FROM ISSUE 2 DUE TO LOST TRACING.
 LA- [Signature]
 ISSUE 3 8-26-46
 "B.S.P. D353.302" WAS SPEC. IN THE TITLE.
 RHD [Signature]
 ISSUE 4 3-21-55 [Signature]



Note:- If filter is not provided connect brown-yellow lead from switch contacts to Y of dial instead of to filter bracket terminal.

LA-

B.S.P. D353.302	
USED ON	DWG.
● - DENOTES MANUFACTURE DISCONTINUED	
304 TYPE TELEPHONE SET	
DRAWN	APPROVED
CHECKED	
WESTERN ELECTRIC CO. INC. ENGINEER OF MANUFACTURE	
LA-	
L	

APPL'S	
DR. R.I.F.	CH. [Signature]
BELL TELEPHONE LABORATORIES, INC. NEW YORK	
ESL-739913	
LA-	