



334 BA, 534P, 537 BA, 538 BA,
545 BA, 546 BA, 534 BA, 584 BA with 78 type ringer
SUBSCRIBER SETS



584 BA with BIAL ringer



434 BA, 634 BA, 637 BA,
638 BA, 645 BA, 646 BA, 684 BA.
SUBSCRIBER SETS

LA-

DIMENSIONS UP TO AND INCLUDING 78 INCHES EXPRESSED IN INCHES

USED ON		DWG.	
●-DENOTES MANUFACTURE DISCONTINUED			
SUBSETS (BELL BOXES) CONNECTIONS			
DRAWN	SCALE	APPROVED	
CHECKED			
WESTERN ELECTRIC CO. INC. ENGINEER OF MANUFACTURE			
LA-			
L			

ISSUE: 1	5-11-38
REDRAWN FROM ISSUE 1 WITH CHANGES IN COMPLIANCE WITH D353.001	
CL:	
ISSUE: 2	8-8-41
IN FIG. 12, 334 BA, 537 BA, 538 BA, 545 BA, 546 BA & IN FIG. 13, 434 BA, 637 BA, 638 BA, 645 BA, 646 BA, WERE NOT SPEC.	
C.B.W.	
ISSUE: 3	7-18-44
FIG. 28 WAS NOT SHOWN.	
D.H.M.	
ISSUE: 4	12-22-47
IN TITLE BOX "CONNECTIONS" WAS "B.S.P. D 353.001" IN VIEW AT UPPER LEFT AT CAPACITOR "1/2 MF" & IN TITLE "WITH 78 TYPE RINGER WERE NOT SPEC. VIEW AT LOWER LEFT WAS NOT SHOWN. FIG. 28" FIG. 12 "FIG. 13" WERE SPEC. FOR UPPER LEFT, UPPER & LOWER RIGHT VIEWS RESP.	
S.E./J.H.	
ISSUE: 5	12-30-58
APPLD	
DR. G.E.H. CH.	ENG. J.E.H.
BELL TELEPHONE LABORATORIES, INC. NEW YORK	
ESL-767970	
LA-	

mw