

83A PROTECTOR MOUNTING

GENERAL

NOTES CONCERNING THIS ADDENDUM

This addendum supplements G38.110.1 with specific information pertaining to the location of plant requiring protection.

The following paragraphs should be marked "See Addendum" and treated as indicated.

Paragraph 3.01(a) - Added "note"

Paragraph 3.02 - Replaced

3. PLANT REQUIRING PROTECTION

3.01(a) Note: In this area 83A protector mountings are not required at the junction between open wire and cable on exchange lines except on those few sections where experience has shown that lightning is prevalent or where such protection is specified in the detail plans. For example, the Imperial Valley, Mojave Desert, and mountain sections are regions where protector mountings should be provided on all exchange lines over 1/2 mile long and on shorter exchange lines where considered necessary because of the frequency of lightning.

3.02 Refer to other sections of the practices covering precautions when connecting or reconnecting non-working open wire.