

PRELASHING
TRANSFERRING

NOTES CONCERNING THIS ADDENDUM

This addendum supplements Section G52.123.6 and has been issued to transfer some incorrectly placed instructions to their proper location in the section.

The cross-reference, "See Addendum", should be written following Paragraph 5.03(6) to indicate the inclusion of additional instructions and at Paragraph 5.04(7) which is cancelled.

5. TRANSFERRING AT CORNER POLES

- 5.03(7) Complete the installation as described in Part 6 of G52.123.6.
- 5.04(7) Cancelled.