

Prepared by
The Pacific Telephone and Telegraph Company
Southern California Area

BELL SYSTEM PRACTICES
Outside Plant Construction
and Maintenance

ADDENDUM G61.901
Issue A, May, 1949-S
T. P. T. & T. Co.

TERMINALS

IDENTIFICATION FOR RECORD PURPOSES

NOTES CONCERNING THIS ADDENDUM

This Addendum supplements Section G61.901 with information relative to Block Terminals and stencilling terminals located on poles in outlying areas.

The cross-reference "See Addendum" should be marked at Paragraph 4.03 to indicate the addition of new information. Paragraph 8.03 is replaced and should be cross-referenced accordingly.

4. IDENTIFYING BLOCK TERMINALS

4.03 Note: A terminal and associated protectors mounted in an enclosed housing on the outside wall of a building, shall be identified in the same manner as a building terminal.

8. STENCILLING TERMINALS IN THE FIELD

8.03 Exchange terminals located on exchange or toll pole lines (on the street, on property lines, or in alleys) situated in outlying areas where street addresses have not been established, shall be stencilled with the number of the toll or exchange pole.