

Distribution Code

CHECKING LIST
 AND INDEX
 CONSTRUCTION AND
 MAINTENANCE FORCES

- A - Dist. Engs., Const. Supts.,
 Supv. Engs., Supv. Const.
 Fore.
- B - Construction Foremen
- C - Splicing and Shop Foremen,
 Chief Cable Testers
- D - Foremen of Cablemen,
 Subway Inspection Group
- E - Splicers
- F - A Cutters

* New or revised since previous
 issue of this section.

% Change in distribution.

<u>Subject</u>	<u>Section</u>	<u>Issue</u>	
	<u>Splicing</u>		
Checking List and Index	*G71.000.1	E	ABCDEF
Cable Terminating - Construction of Forms	G71.135 Add. G71.135	A 2	A-C---
Cable Terminating - Ordering and Installing Cable Forms	G71.136 Add. G71.136 Add. G71.136	A 1 2	A-C---

<u>Subject</u>	<u>Section</u>	<u>Issue</u>	
<u>Splicing (Continued)</u>			
Cable Terminating - Termination of Cables in Buildings	G71. 137 Add. G71. 137	A 1	A-C---
Cable Terminating - Forms for Toll Cables	G71. 138	1	A-C---
Buried Cable Loading	G71. 170	1	A-C---
Spiral-four Disc-insu- lated Cable.	G71. 185 Add. G71. 185 Add G71. 185	2 A 1	A-C---
Terminating K Carrier Cables	G71. 189	1	A-C---
Terminating K Carrier Cables - Planned Splices for Successive Repeater Stations (On Quadded Cable Routes) to Mini- mize Recurrence of Same Two K Systems in a Quad	G71. 190 Add. G71. 190	1 1	A-C---
Distributing Frame Cross-connections	G71. 199	3	A-C---
Tension Splicing	G71. 530	2	A-C---
Submarine Cable Splicing - General	G71. 705	1	A-----
Overlap Armor Wire Method	G71. 710	1	A-----
Welded Armor Wire Method	G71. 720	1	A-----
Splicing Cable with Channel Wire Joining Tool	G71. 901	A	A-C---

General Procedures for
Thermoplastic - Copper
Jacketed Cable

G71.904.1

B

A-----

Splicing Thermoplastic
Copper and Corrosion
Protected Cable

G71.904.4

B

A-----

Thermoplastic - Copper
Protected Cables -
Pressure Testing

G71.904.5

A

A-----