

Distribution Code

- A - Dist. Engs. , Const. Supts.,  
 Supv. Engs. , Supv. Const.  
 Fore.
- B - Construction Foremen
- C - Splicing and Shop Foremen,  
 Chief Cable Testers
- D - Foremen of Cablemen,  
 Subway Inspection Group
- E - Splicers
- F - A Cutters

CHECKING LIST  
 AND INDEX

CONSTRUCTION AND  
 MAINTENANCE FORCES

\*New or revised since previous  
 issue of this section.

%Change in distribution.

<u>Subject</u>	<u>Section</u>	<u>Issue</u>	
	<u>Pressure Testing</u>		
Checking List and Index	*G73.000.1	H	ABCDEF
General - Description of Tests and Systems	G73.005.1	1	A-C---
General - Layout of Pressure Systems	G73.005.2	1	A-C---
General - Continuous Flow Systems	G73.009.1-S	A	A-C---
Pressure Testing - Con- tinuous Flow Systems For Exchange Cables	*G73.009.2	A	A-C-E-
Pressure Testing - Con- tinuous Flow Systems For Trunk Cables	*G73.009.3	A	A-C---

<u>Subject</u>	<u>Section</u>	<u>Issue</u>	
<u>Pressure Testing (Continued)</u>			
Pneumatic Resistance of Cables	G73.016.1	1	A-C---
Nitrogen Gas Cylinders	*G73.056.1	2	A-C-E-
Sulfur Hexafluoride Gas	G73.056.2	1	A-C---
Freon 12 Gas	G73.056.3	1	A-C---
Solutions and Accessories	G73.058.1	1	A-C-E-
Precautions	G73.090.1	1	A-C-E-
Valves - Lead Cable and Sleeves	G73.105.1	1	A-C-E-
Flanges and Screw Plugs - Lead Cable and Sleeves	G73.105.2 WR G73.105.2 Add. G73.105.2	1 A 1	A-C-E-
Valves, Flanges, and Ells- Alpeth or Stalpeth Cable	G73.105.5	1	A-C-E-
Sheath Preparation for Fittings - Lead Sheath	G73.106.1	1	A-C---
Sheath Preparation for Valves - Lepeth Sheath	G73.106.2	1	A-C---
Arrangement of Valves	G73.110.1	1	A-C-E-
B By-Pass Valve	G73.115.1	1	A-C-E-
Arrangement of Gas By- Passes	G73.117.1	1	A-C---
Soldering Molds	G73.125.1	1	A-C-E-
Contactors and Contactor- Terminals - Description	G73.130.1	1	A-C---
Contactors and Contactor - Terminals - Checking Operating Pressure	G73.130.2	1	A-C---

Contactors and Contactor - Terminals - Replacement of Contactor Mechanism	G73.130.3	1	A-C----
Splice Type Contactors	G73.133.1	1	A-C----
37-Type Terminal - Description	G73.137.1	2	A-C----
37-Type Terminal - Wiring Diagrams	G73.137.2	1	A-C----
Contactors and Contactor - Terminals - Superseded Type	G73.140.1	1	A-C----
Terminals - Superseded Type	G73.141.1	1	A-C----
Mounting Contactors and Terminals	G73.145.1	1	A-C----
Arrangements at Contactor Points - Aerial Cable	G73.145.2	1	A-C----
Arrangements at Contactor Points - Underground Cable	G73.145.3	1	A-C----
Arrangements at Contactor Points - Buried Cable	G73.145.4	1	A-C----
Preparing Materials for Pressure Plugs	G73.150.1	1	A-C----
Asphalt-Filled Horizontal Plugs - Cable Entering Sleeve From Both Ends	G73.151.1	1	A-C----
Asphalt-Filled Horizontal Plugs - Cable Entering Sleeve From Same End	G73.151.2	1	A-C----
Gas Plugs - Lepeth Sheath Cable	G73.151.3	1	A-C----

<u>Subject</u>	<u>Section</u>	<u>Issue</u>	
<u>Pressure Testing (Continued)</u>			
Wax Filled Horizontal Plugs	G73. 152. 1	1	A-C---
Alphalt-Filled Vertical Plugs	G73. 153. 1	2	A-C---
Lead Sleeve Type Terminal Plugs	G73. 155. 1	1	A-C---
Pressure Gun Type Asphalt Plug	G73. 156. 1	1	A-C---
Cold Resin Pressure Plug	G73. 157. 1-S	A	A-C-E-
Reinforcing Lead Sleeves	G73. 164. 1	1	A-C-E-
Buried Cable - Thermometer Wall	G73. 166. 1	1	A-C---
Installing ZA Pressure Plug	G73. 170. 1	1	A-C---
Auxiliary Reservoirs - Equipment	G73. 180. 1	1	A-C---
Auxiliary Reservoirs - Installation	G73. 180. 2	1	A-C---
Correction of Pressure Measurements - General	G73. 205. 1	1	A-C---
Atmospheric Pressure	G73. 205. 2	1	A-C---
Temperature	G73. 205. 3	1	A-C---
Altitude Correction for Ordinary Measurements	G73. 205. 4	1	A-C---
Altitude Correction for Precise Measurements	G73. 205. 5	1	A-C---
Pressure Testing - Altitude Correction for SF6 Gas (Long Lines Issue)	G73. 205. 6	A	A-C---

Gas Flow Indicators	G73. 210	3	A-C---
Construction Tests - General	G73. 225. 1	1	A-C-E-
Construction Tests - Procedure During Placing	G73. 225. 2	1	ABCDE-
Construction Tests - Procedure During Splicing	G73. 225. 3 Add. G73. 225. 3	C 1	A-C-E-
Construction Tests - Three-Section Method Of Leak Location	G73. 225. 4	1	A-C-E-
Pressure Testing - Maintaining SF6 Filled Cables under Pressure (Long Lines Issue)	G73. 231. 9	A	A-C---
Charging Cables With Gas	G73. 305. 1	1	A-C---
Initial Charging Coaxial Cable With SF6	G73. 306. 1	1	A-C---
Charging Cable With Freon 12	G73. 307. 1 Add. G73. 307. 1	A 1	A-C---
Maintaining Cables Under Pressure - General	G73. 310. 1	1	A-C---
Maintaining Cables Under Pressure Maintaining Pressure	G73. 310. 2	1	A-C---
Maintaining Cables Under Pressure - Contactor Operation	G73. 310. 3	1	A-C---
Maintaining Cables Under Pressure - Sheath Open- ings	G73. 310. 4	1	A-C---

<u>Subject</u>	<u>Section</u>	<u>Issue</u>	
<u>Pressure Testing (Continued)</u>			
Records and Maintenance Summary	G73. 320. 1	2	A-C---
Location of Gas Leaks - Principles of Leak Location	G73. 415. 1	1	A-C---
Location of Gas Leaks - Making Pressure Readings	G73. 415. 2	1	A-C---
Location of Gas Leaks - Plotting Pressure Gradients	G73. 415. 3	1	A-C---
Location of Gas Leaks - Analysis of Pressure Gradients	G73. 415. 4	1	A-C---
Location of Gas Leaks - Computing Leak Location	G73. 415. 5	2	A-C---
Leak Location Procedures - General	G73. 417. 1	1	A-C---
Leak Location Methods - Two-Direction Method	G73. 418. 1	1	A-C---
Leak Location Methods - Two-Cable Method	G73. 418. 2	1	A-C---
Leak Location Methods - Time-Pressure Curves	G73. 418. 3	1	A-C---
Leak Location Methods - Two-Cylinder Method	G73. 418. 4	1	A-C---
Leak Location Methods - Short-Circle Method	G73. 418. 5	1	A-C---
Leak Location Methods - One-Cylinder Method	G73. 418. 6	1	A-C---

Precision Leak Locating - Procedure	G73.421.1	1	A-C---
B Leak Locator - General	G73.430.1	1	A-C---
B Leak Locator - Testing Procedure	G73.430.2	1	A-C---
Maintaining Defective Section Under Pressure	G73.436.1	1	A-C---
Use and Maintenance of Alcohol Manometers (Long Lines Issue)	G73.921.1 Add. G73.921.1	A A	A-----