

PRESSURE TESTING  
B LEAK LOCATOR - DETECTOR

NOTES CONCERNING THIS ADDENDUM

This addendum supplements Section G85.145.3 and is being issued to make the following corrections.

3. OPERATING TESTS

- 3.09 (4) Should read "Then adjust the SIGNAL CURRENT to 1/2 ma below maximum."
- 3.10 Practice reference in third line should be changed to "G85.145.1."