

B POLE STEPS  
INSPECTION FOR CRACKS

NOTES CONCERNING THIS ADDENDUM

This addendum supplements G86.195.1 and is being issued to provide that all B pole steps be inspected before using.

"See Addendum" should be marked at Paragraph 2.01(a) which is hereby replaced.

2. INSPECTION OF STEPS

(a) Examine closely all older type B pole steps before using.

Pay particular attention to the underside of the steps where the metal is bent, and at the inside of the corners at the top of the mounting slot. These locations are shown in the sketch following Paragraph 2.01(a) in the main section which should not be crossed out.