

MEASURING TAPES

WOVEN

NOTES CONCERNING THIS ADDENDUM

This addendum supplements Section G86.510.1 and is being issued to modify instructions pertaining to measuring tapes that do not have green identification markings.

The cross reference "See Addendum" should be written at Paragraph 3.01 which is supplemented.

3. PRECAUTIONS

3.01 Woven tapes without the green identification markings may be used provided there is no possibility of contacting energized plant.