

BELL SYSTEM PRACTICES
Teletypewriter Stations

ADDENDUM P30.433
Issue 1, June, 1957
AT&TCo Standard

POWER CONNECTIONS

15A TELETYPEWRITER TABLE

1. GENERAL

1.001 This addendum supplements Section P30.433, Issue 2.

1.002 This addendum is issued to change information on the type switch assembly shown in wiring plan P3.12 of the section. The line cut in the section shows part of a Hubbell BL11253 switch assembly which has been manufacture discontinued and replaced with one of the following:

- (a) Hubbell or P & S 1317 Switch
- (b) P & S DS-1595 Switch Assembly