



SUPPLEMENTARY POWER CONNECTIONS

1. GENERAL

(New Paragraphs)

- 1.01 Plan PSA 1.01 covers changes necessary on various PM plans when the KS-5579 rectifier is to be used.
- 1.02 Plan PSA 1.02 covers the connections of the KS-5579 rectifier.



PSA 1.01
Mod. of PM 2.06, 2.07
2.10, 2.11, 2.12, 2.13, 2.14
2.15, 2.16, 4.03, 4.05, 4.10
and 4.11 when KS 5579
Rectifier is used

PSA 1.02
KS 5579 Rectifier for
14 & 15 Type TTY