

BELL SYSTEM PRACTICES  
Teletypewriter and Data Stations

ADDENDUM P34.004  
Issue 1, May, 1958  
AT&T Co Standard

## MOTORS AND GOVERNORS

### 28 TELETYPEWRITER

### REQUIREMENTS AND PROCEDURES


#### 1. GENERAL

- 1.001 This addendum supplements Section P34.004, Issue 1.  
1.002 This addendum is issued to add a caution on the operation of synchronous motors.

#### 2. REQUIREMENTS AND ADJUSTING PROCEDURES

The following paragraph replaces Paragraph 2.02 of the Section.

##### 2.02 Synchronous Motor



ADDENDUM  
P34.004

Page 1  
1 Page

MOTORS AND GOVERNORS  
28 TELETYPEWRITER  
REQUIREMENTS AND PROCEDURES