

BELL SYSTEM PRACTICES
Teletypewriter and Data Stations

ADDENDUM P34.403
Issue 1, May, 1961
AT&T Co Standard

28 MOTOR UNIT

DISASSEMBLY AND REASSEMBLY ROUTINES

1. GENERAL

1.001 This addendum supplements Section P34.403, Issue 1.

1.002 This addendum is issued to include the disassembly and reassembly routines for the removal of a 28 motor unit from a 28 sequence selector base.

2. DISASSEMBLY AND REASSEMBLY

The following change applies to Part 2 of the section:

(a) 2.01.1—added

2.01.1 Removal of 28 Motor Unit from 28 Sequence Selector Base

- (1) Remove the sequence selector unit from the sequence selector base in accordance with the section entitled 28 Sequence Selector Unit and Base, Disassembly and Reassembly Routines.
- (2) Remove the motor unit in accordance with the procedures given in 2.01(2) to 2.01(5), inclusive.

Reassembly Note

1. Check, and if necessary remake, the intermediate-gear bracket assembly adjustment specified in the section giving requirements for 28 teletypewriter base.