

BELL SYSTEM PRACTICES
Teletypewriter and Data Stations

ADDENDUM P34.501
Issue 2, February, 1962
AT&TCo Standard

28 TYPING UNIT

LUBRICATION

1. GENERAL

1.001 This addendum supplements Section P34.501, Issue 1.

1.002 This addendum is reissued to add information concerning adjustments which must be checked after each routine servicing.

The following change applies to Part 1 of the section:

(a) 1.03—added

1.03 Each time the 28 teletypewriter is given routine servicing, the adjustments listed in **PARTS REQUIRING ROUTINE CHECK** in the section covering requirements and adjustments of the 28 typing unit should be verified and, if necessary, remade in accordance with that section.

3. LUBRICATION DETAILS FOR VARIABLE FEATURES

The following change applies to Part 3 of the section:

(a) 3.25—added

3.25 Form-feedout Mechanism

