

American Telephone and Telegraph Company
Printed in U.S.A.

BELL SYSTEM PRACTICES
Teletypewriter and Manual
Telegraph Station and PBX
Installation and Maintenance

ADDENDUM P38.901
Issue A, May 1959
Long Lines Department
Dist. Class. 600AC

TELEGRAPH

LINE FEED COUNTER

NO. 19 TELETYPEWRITER SET

1. GENERAL

- 1.00 This addendum supplements Section P38.901, Issue B.
- 1.01 This addendum is issued to:
- (a) Replace Engineering Staff Drawing 20403-106 with a Western Area Drawing WA-13516 in accordance with the program to disburse these drawings.
 - (b) Correct a difficulty in assembly of the Line Feed Counter.

2. MATERIAL REQUIREMENTS

- 2.01 In the set of special contacts described in Figure 1 the TP 1051 screw was TP1026. Additional dimensions are shown in mounting detail shown in Figure 3.

7. REFERENCES

- 7.01 Change this paragraph to read "Figures 1 to 10 inclusive are reproduced from Western Area Drawing WA-13516".