



NOTES:  
1. SOME 128B2 SUBSCRIBER SETS DO NOT INCLUDE THE (AT) RES. AND WHEN THE KS-5663, L4 OR L7 RECTIFIER IS USED A CHECK SHOULD BE MADE TO INSURE THAT THE (AT) RESISTANCE IS PRESENT.

STATION IDENTIFICATION

19 TTY - 19A TABLE  
TWP SERVICE - 128B2 TTY SUB SET  
SINGLE LOOP OPERATION  
EMERGENCY TTY OPTIONAL