

W.C. - Garden City

BELL
TELE
INSTALLA




FIG. A






FIG. B










FIG. C

- NOTE:**
1. MOUN
OR S
 2. ADJU
A-43
 3. NEW
BY II

BELL SYSTEM PRACTICES
TELETYPEWRITER STATION
INSTALLATION AND MAINTENANCE

SECTION P90.970
ISSUE B JULY, 1946
LONG LINES DEPT.

REPRODUCED FROM DWG. 21647-131



NOTES

1. MOUNT ON TELETYPEWRITER TABLE PER PLAN SA5.02 OR SA6.03.
2. ADJUST KEY IN ACCORDANCE WITH BSP SECTION A-432.019.
3. NEW WIRING INDICATED BY HEAVY LINES TO BE ADDED BY INSTALLER.

TELEGRAPH SYSTEMS
KEY TO TRANSMIT A 5 SECOND
BREAK SIGNAL