

TP115408 CONTACT PLUNGER

APPARATUS AFFECTED: BS3C sequential selector (#1 type Sotus).

CHANGE: The TP115408 contact plunger is now being made of a better grade of bakelite, Spauldite XXX-618, and is held to a straightness tolerance of .005". The diameter tolerance is now being held to +.003"-.005" instead of +.005".

INTERCHANGEABILITY: New and old style parts are interchangeable.

W.E.CO. STOCK OF OLD PARTS: None.

APPLICATION TO NEW APPARATUS: This change is now in effect.

APPLICATION TO EXISTING APPARATUS: Old style parts that are giving satisfactory service need not be replaced.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: Old style parts when defective shall be replaced by new style parts.

IDENTIFICATION: The only means of identification is to check for conformity to straightness tolerance.

REASON FOR CHANGE: To provide contact plungers that are less liable to become distorted.