

TP122276 BLOCKING LEVER ASSEMBLY

APPARATUS AFFECTED: BS3C sequential selector.

CHANGE: The one-piece TP115219 blocking lever is being superseded by a two-piece TP122276 blocking lever assembly consisting of the following parts:

1 - TP122277 bracket	1 - TP3599 nut
1 - TP122278 clutch blocking lever	1 - TP1200 screw, 6-40
1 - TP1174 shoulder screw, 4-40	1 - TP2191 lockwasher
1 - TP3640 lockwasher	1 - TP7002 washer

INTERCHANGEABILITY: New and old style assemblies are interchangeable.
Component parts are not interchangeable.

W.E.CO. STOCK OF OLD PARTS: May be used.

APPLICATION TO NEW APPARATUS: This change is being incorporated as soon as stock and manufacturing conditions permit.

APPLICATION TO EXISTING APPARATUS: When they become available, new style parts may be applied when old style parts are removed for any reason.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: Units may be equipped with new or old style parts.

IDENTIFICATION: New style parts may be identified by the two-piece construction.

REASON FOR CHANGE: To facilitate adjustment of the main shaft clutch without disturbing the stripper bail.