

AMERICAN TELEPHONE AND TELEGRAPH COMPANY

195 BROADWAY, NEW YORK 7, N.Y.

AREA CODE 212 393-3452

R. F. DAVIS
CUSTOMER TELEPHONE PRODUCTS PLANNING ENGINEER

May 8, 1962

P.E.M. 7956

Topical Index Code 1C1.15A

In the past, the small cordless attendant equipment which has been used with dial PBX systems has been called a variety of things - none of which were too descriptive of the equipment unit's function. For example, the first attendant equipment used with the 756A PBX was called a "Modular Station Unit". Later, this was replaced by the 610 "Telephone Set".

In order to aid in certain accounting functions, the nomenclature for the telephone sets listed below has been changed to refer to them as "Telephone Consoles". In general, the term "Telephone Console" will be applied to consoles which include an attendant's telephone circuit. Consoles which perform other functions will be coded accordingly - for example, the 100 line and 200 line D.S.S. (Direct Station Selection) consoles described under the Universal Console in P.E.L. 6916 will be coded 1A and 2A "Selector Consoles".

New Code Telephone Console	Old Code Telephone Set To be Mfr. Disc.	Tel. Console Mtg. Cord	Used With
1A-	None - see note 1	None-see note 1	#5-701-757-EPBX
2A-	" "	" "	"
3A1-*, 3A2-*	610B1-*, 610B2-*	D100A-*	756 PBX
4A1-*, 4A2-*	612A1-*, 612A2-*	D200D-*	756 (DSS)
5A1-*, 5A2-*	None - see note 2	D100C-*	701-740
6A1-*, 6A2-*	615A1-*, 615A2-*	D200E-*	701-740
7A1-*	620A1-*	D150A-*	701 (Interim)
8A1-*, 8A2-*	621B1-*, 621B2-*	D150E-*	701 "
9A1-*, 9A2-*	622A1-*, 622A2-*	D150C-*	#5 XB "

*Each code includes the color significant suffix -51 (green), -58 (white), -60 (light beige) and -61 (light gray).

Note 1. The 1A- and 2A- telephone console codes have been assigned to the "Universal Consoles" which will be described in a future P.E.L.

Note 2. The 5A1, 5A2 telephone console codes have been assigned to a new console which will be similar to the 6A type telephone consoles with the busy lamp field omitted. These will be used with 701-740 type PBXs where a 1 position console is desired, and will be described in more detail in a future P.E.L.

"C" Practices for these consoles will be issued as follows:

<u>Telephone Console</u>	<u>Identification and Assembly of Parts</u>	<u>Estimated Availability</u>	<u>Connections</u>	<u>Estimated Availability</u>
1A	C38.721.00*	6-1-62	C38.721.01	6-1-62
2A	"	"	"	"
3A	C38.722.00*	6-15-62	C38.722.01	Now
4A	"	"	C38.722.02	"
5A	C38.723.00*	7-1-62	C38.723.01	Now
6A	"	"	"	"
8A	C38.724.00	Iss. 1 - Now	C38.724.01	"
9A	"		C38.724.02	6-1-62

* In the interim practices covering "The Call Director" sets may be used.

Telephone console installation and maintenance will be covered in C38.720.01 available about June 1, 1962. In the interim appropriate sections of the practices covering "The Call Director" sets may be used.

The Western Electric Company advises that all "Telephone Consoles" except the 1A, 2A and 5A are now available on order and the corresponding "Telephone Sets" have been rated manufacture discontinued.

R. F. Davis

Customer Telephone Products Planning Engineer

To all Chief Engineers
(Copies included for
General Plant Managers)