

RIL #8

June 7, 1977

j

Dear j:

The Tandem Screening Office paragraph on page 4 of the attachment to my May 5th letter on WATS tariff changes, needs some clarification and contains some erroneous information. Inward WATS Tandem Screening Offices should not have to make changes if they are 4A ETS or 4 ESS. These offices send out the same "C" digit they receive and therefore there is no need to make any changes, they depend on the OSO for the correct digit and merely regenerate it.

The card translator (and others) will have changes to make if the cards (or wiring) is not there under the correct system code for proper translation and code conversion.

Also in the fourth sentence of that paragraph (the example), delete the portion "and 085 + 241 + 4D to 143 + 4D". The phrase is wrong and should not have been included.

W. B. Plossl
Supervisor - Network Trunk Administration