




# 2003-2007 Honda Accord Auto Tensioner Replacement

A video tutorial on how to change the auto tensioner on a 2003-2007 Honda Accord.

Written By: eCuration



## INTRODUCTION

A squeak in your engine bay is usually a first sign that the drive belt tensioner is going out.

Follow this video tutorial by YouTuber [NutzAboutBolts](#) to complete the replacement yourself.

### TOOLS:

- [3/8" Drive Ratchet \(1\)](#)
- [14mm Deep Socket \(1\)](#)
- [12mm Deep Socket \(1\)](#)

### PARTS:

- [Auto Tensioner \(1\)](#)

To reassemble your device, follow these instructions in reverse order.