




2003-2007 Honda Accord Power Steering Pump Replacement

A video tutorial on how to change an old worn out power steering pump on a 2003-2007 Honda Accord.

Written By: eCuration



This document was generated on 2019-09-23 01:05:49 PM (MST).

INTRODUCTION

If you are noticing a power steering leak, squealing sound when turning and or difficulty turning then it may be time to replace the power steering pump.

Follow this video tutorial by YouTuber [NutzAboutBolts](#) to complete the repair yourself.

TOOLS:

- 3/8" Drive Ratchet (1)
- 12mm Deep Socket (1)
- 10mm Deep Socket (1)
- Hose Clamp (1)
- Large Needle Nose Pliers (1)
- Paper Towels (1)
- Torque Wrench (1)

PARTS:

- Power Steering Pump (1)

To reassemble your device, follow these instructions in reverse order.