



# 2005-2015 Nissan Xterra Tie Rod End Replacement

A video tutorial on how to replace a tie rod on a 2005-2015 Nissan Xterra.

Written By: eCuration



## INTRODUCTION

If you are experiencing shaking in the steering wheel while driving, loose steering, and or noises when hitting a bump, then it may be time to replace your tie rod ends.

Follow this video tutorial by YouTuber [Ry The Car Guy](#) to complete the replacement yourself.

## Safety

If this is your first time working on a vehicle read our [safety tips](#) before proceeding.

### TOOLS:

- [Hydraulic Floor Jack](#) (1)
- [Jack Stand](#) (1)
- [Wheel Chocks](#) (1)
- [3/8" Drive Ratchet](#) (1)
- [21mm Socket](#) (1)
- [Large Needle Nose Pliers](#) (1)
- [Adjustable Wrench](#) (1)
- [Pickle Fork](#) (1)
- [Penetrating Lubricant](#) (1)
- [White Out](#) (1)

### PARTS:

- [Steering Tie Rod End](#) (2)

To reassemble your device, follow these instructions in reverse order.