



Acer Aspire V3-551-8469 USB Port Replacement

Use this guide to replace an Acer Aspire V3-551-8469 USB port.

Written By: Maritsa Garcia




INTRODUCTION

If your laptop isn't downloading data into a plugged in USB device, the USB port will need to be replaced. Use this guide to replace broken USB ports in your Acer Aspire V3-551-8469 laptop. No complicated manipulation is required.

TOOLS:



- [Phillips #0 Screwdriver](#) (1)
- [Phillips #00 Screwdriver](#) (1)
- [Spudger](#) (1)

Step 1 — USB Port




- To release the battery, slide the orange tab to the right with a spudger.
- The battery is now released and can be picked up and set to the side.

Step 2




- Remove the sixteen 5.3 mm Phillips #0 screws.
- Remove the three 3 mm Phillips #00 screws.

Step 3



- Flip the computer over and remove the touchpad cover.

Step 4




- Remove the ribbon cable connecting the USB ports to the computer.

Step 5



- Using a Phillips #0 screwdriver, remove the one screw.

Step 6



- Slide the USB port out.

To reassemble your device, follow these instructions in reverse order.