



Adjusting Contrast on TI-Nspire Calculator

This guide will aid in adjusting the contrast settings of the TI-Nspire Calculator.

Written By: Alan Wong



INTRODUCTION


If your calculator does not appear to light up, it could be that the contrast is at a low setting. Use this guide to aid you in adjusting the contrast.

Step 1 — Adjusting Contrast on TI-Nspire Calculator



- Remove the front protective cover by sliding it off of the calculator.
- Press the "ON" button to turn on the calculator.

Step 2



- Press the "2ND" button at the top left portion of the keypad. An arrow pointing up will appear at the top left corner of the screen.
- Press and hold the "UP" arrow until you have increased the contrast to a level that is easily visible for yourself. A common level to set the contrast is 5.
- To decrease the contrast, press the "2ND" button, then press and hold the "DOWN" arrow.

Now you should have the image contrast set to your preferences.