



Audio-Technica ATH-S200BT Microphone Hole Fix

Drill a microphone hole for the Audio-Technica ATH-S200BT microphone.

Written By: yodji suzuki



INTRODUCTION

By the default, the headphones have no hole for the microphone so the voice sounds very terrible.

To fix this issue, you should teardown the left monitor and drill a hole about 1 mm hole in front of the mic.

Step 1 — Audio-Technica ATH-S200BT Microphone Hole Fix



- Remove the 3 screws holding the left headphone cup together.

Step 2



- Separate the three enclosure parts by hand.

Step 3



- Drill a hole about 1 - 1.5mm hole.

Step 4



- Reassemble the headphone PCB.

To reassemble your device, follow these instructions in reverse order.