



Bendix Magneto Impuse coupling replacement

Steps to remove the Bendix Magneto impulse coupling.

Written By: Kelsi English





INTRODUCTION

A failed impulse coupling can cause the crankshaft gear to break off. This will cause the aircraft's magneto not to work therefore the aircraft's engine will not start.

TOOLS:


- 9 16 wrench (1)
- Large Needle Nose Pliers (1)

Step 1 — Impulse Coupling




- Use a 9/16 wrench to unscrew the nut on the drive shaft.

Step 2



- Remove the lock washer underneath the nut.

Step 3



- Pull away the impulse coupling.

To reassemble your device, follow these instructions in reverse order.