



BlackBerry 7510 Antenna Replacement

Written By: Neil Johnson



INTRODUCTION

This guide will instruct on how to extract the antenna from the RIM BlackBerry 7510 and replace it with a new one.

TOOLS:

- [T6 Torx Screwdriver](#) (1)

Step 1 — Back Cover




- Unscrew all six visible screws.

Step 2




- Pry open back plate using spudger.

Step 3 — Antenna



- Unscrew antenna from back cover.

Step 4



- The bad antenna is now removed and may be replaced.

To reassemble your device, follow these instructions in reverse order.