



BlackBerry 7510 Vibration Motor Replacement

How to replace a BlackBerry 7510 vibration motor.

Written By: Neil Johnson



INTRODUCTION

This will show you how to repair the vibrating motor in your blackberry.

TOOLS:

- T6 Torx Screwdriver (1)

Step 1 — Back Face of Phone



(i) Remove the battery cover and battery before continuing.

- Remove the six T6 Torx screws on the back of the phone.
- Make sure to keep the screws somewhere that they will not get lost.

Step 2



- Using your finger nail or a spudger, carefully pry up the back cover.
- Begin in one spot and slowly circle around the device as you pry up all of the back cover.

Step 3




- Lift off the back cover.

Step 4



- Remove the two T6 screws.

Step 5



- Remove the daughterboard.
- Remove the exposed vibration motor.

Step 6 — Vibration Motor



- Replace with new vibration motor.

To reassemble your device, follow these instructions in reverse order.