




# Brother IntelliFax-2840 Automatic Document Feeder Replacement

Replace the automatic document feeder in your IntelliFax-2840.

Written By: Geoff Wacker




## INTRODUCTION

Use this guide to replace the automatic document feeder (ADF) on your Brother IntelliFax-2840.

### TOOLS:

- Phillips #1 Screwdriver (1)

## Step 1 — Automatic Document Feeder



- Remove the two 15 mm Phillips #1 screws securing the ADF at the rear of the fax machine.

## Step 2



- Gently pull the ADF up and away from the machine.

To reassemble your device, follow these instructions in reverse order.