



Epiphone ES-335 PRO Tuner Replacement

Replace a faulty or broken tuner on your guitar to make your guitar look new.

Written By: Michaih Ley Bayani



INTRODUCTION

Follow these steps to replace a faulty or broken tuner at the head of the Epiphone ES-335 PRO electric guitar. This component of the guitar can also be changed to upgrade the design of the guitar to your liking.

TOOLS:


- Phillips #2 Screwdriver (1)

Step 1 — Strings



- Using the tuner, loosen the string by turning the tuner.
- Continue to loosen the string until it is easily unwrapped and pulled out of the tuner.

Step 2



- On the bridge of the guitar, push the string through the back until the other end is visible. Then grasp and pull the string all the way out.

Step 3 — Tuner



- Using a phillips head #2 screwdriver, unscrew the two 1.0 mm length screws on the sides of the tuner.
- i* Be sure to keep track of the screws if you are using them for the new tuner, unless the new tuner has screws of its own.

Step 4



- The tuner should come right out of the back of the head of the guitar.

To reassemble your device, follow these instructions in reverse order.