




# Escort Passport 9500IX Button Board Replacement

This guide will help you with replacing your Escort Passport 9500IX button board.

Written By: Kennedy Morales



## INTRODUCTION

Are the buttons on your radar not responsive? If so, the button board could be damaged. Follow this guide to replace your button board.

### TOOLS:

- [Phillips #1 Screwdriver](#) (1)
- [Spudger](#) (1)

## Step 1 — Back Panel




- Remove the three 1.2 mm Phillips #1 screws on the back of the device.

## Step 2




- Pry off the back panel of the radar using the nylon spudger.

## Step 3 — Buttons




- Carefully pry the grey frame off the black plastic covering using the nylon spudger.

## Step 4




- Slowly peel the buttons off the button board.

## Step 5 — Button Board




- Detach the orange flap on the motherboard.
- Carefully remove the motherboard from the grey plastic frame.

## Step 6



- Detach the orange flap directly behind the button board.

## Step 7



- Carefully pull out the button board from the grey frame.

To reassemble your device, follow these instructions in reverse order.