




Fosera Scandle 200 Charging Terminal Replacement

In this guide instructions will be given on how to remove a charging terminal in the case that it stops working.

Written By: David



INTRODUCTION

This guide will explain and show how to replace a charging terminal that has stopped working. Replacing it requires the use of a soldering iron and the Spudger. This is a fairly easy replacement guide and should only take around fifteen minutes.

TOOLS:

- [Phillips #0 Screwdriver](#) (1)
- [Spudger](#) (1)
- [Soldering Iron](#) (1)

Step 1 — Motherboard Removal




- To open up the casing, you will need to unscrew the four Phillips #0 15mm screws which are accessible from the back.

Step 2




- Gently separate the two halves of the casing.

Step 3




- Disconnect the battery from the motherboard by lifting up on the white plastic tab on the top of the connection.
- Gently pull the cord out by the white plastic adapter. Do not pull from the red and black cord.

Step 4




- Unscrew the Phillips four #0 15mm screws to free the motherboard from the casing.

Step 5



- Slowly pull the motherboard out of the casing. Make sure the loose battery wire doesn't get snagged.


Step 6 — Charging Terminal



 Use caution when using a soldering iron, the tip will be very hot.


- Locate the charging terminal's three prong connectors on the back of the motherboard.

Step 7



- Start melting the solder on each prong connector individually with the soldering iron.

Step 8



- Use the flat end of the spudger to pry the charging terminal away from the motherboard.

To reassemble your device, follow these instructions in reverse order.