




HP Mobile Thin Client mt41 Portal Replacement

This guide will show you how to remove the charging port.

Written By: Raul Rodriguez



 **TOOLS:**

- [iFixit Opening Tools \(1\)](#)
- [T5 Torx Screwdriver \(1\)](#)
- [Spudger \(1\)](#)
- [Pro Tech Toolkit \(1\)](#)


Step 1 — Back Cover



- Locate the screws highlighted to remove.

(i) We recommend removing the battery first. Refer to the "Battery Replacement" guide to learn how to remove the battery.

Step 2



- Remove the middle back lid shown in the image.

(i) May require a bit of force. If it is not coming out try the other side.

Step 3



- Go around the edges with a special tool to pop lid out of place.


Step 4



- Once all corners are popped out of place lift the cover up slowly.

i Lifting the lid should not require much force.

Step 5 — Charging port





- Locate the battery port.
- *i* refer to the "Lower case disassembly" guide to show you how to safely remove the back of the laptop.

Step 6



- Remove the screw next to the battery port.
- Gently pull out the charging port.

Step 7



- Unplug the connector shown in the image. This should not require much force.

To reassemble your device, follow these instructions in reverse order.