



Huawei P10 USB Port Replacement


This video is about how to repair the broken USB port of Huawei P10.

Written By: Witrigs

P10

USB Board

Repair Guide



INTRODUCTION

[video: https://www.youtube.com/watch?v=TIN8_W8sFvI]

This video shows you how to repair the broken usb port of huawei p10. If your phone can not charge or connect to laptop, follow this repair guide to fix the broken usb port.



TOOLS:

- [Mako Driver Kit - 64 Precision Bits](#) (1)
 - [SIM Card Eject Tool](#) (1)
 - [iFixit Opening Tools](#) (1)
 - [Spudger](#) (1)
 - [Tweezers](#) (1)
-

Step1 Open the battery cover of Huawei P10

Step2 Remove the broken USB board

Step3 Install a new USB board

Step4 Instal battery cover of huawei P10