



Keurig Elite Solenoid Replacement

Fixes Keurig's suffering from slow brew/drip and no brew.

Written By: Stephen Ford



TOOLS:

- [Phillips #2 Screwdriver](#) (1)
- [Soldering Iron](#) (1)



PARTS:

- [CJV23-C12A1](#) (1)
- [Solder](#) (1)
- [Rosin Flux](#) (1)

To reassemble your device, follow these instructions in reverse order.