




Kicker CXA300.1 Capacitor Replacement

Replace the capacitor in the Kicker CXA 300.1 Amplifier

Written By: Tim Keptya



INTRODUCTION

Follow this guide to replace a capacitor in a Kicker CXA 3001 amplifier.

TOOLS:

- [T10 Torx Screwdriver](#) (1)
- [Portable Soldering Iron](#) (1)
- [2mm Hex Key](#) (1)
- [Soldering Iron](#) (1)

Step 1 — Capacitor




- Remove the five T10 Torx screws from the housing.

Step 2



- Remove the two T10 Torx screws from the faceplate.

Step 3



- Remove the six T10 Torx screws from the bottom.
- Pull off the bottom.

Step 4



- Desolder the capacitor and remove.

Step 5



- Refer to iFixit's soldering [guide](#) to reattach capacitor.

To reassemble your device, follow these instructions in reverse order.