



MiTM Pressure Washers CA2703HDHB1 2017

Recoil Starter Replacement

Remove and replace the recoil starter assembly for the MiTM CA2703 pressure washer.

Written By: Arthur Shi



This document was generated on 2020-04-05 07:46:05 PM (MST).

INTRODUCTION

This guide shows how to remove and replace the entire recoil starter assembly. The assembly is an OEM part for Honda GX200 engine models.


If you replace the recoil starter with a non-OEM part, you may have to remove the starter cap.
For that, you will need the following additional tools:

- 3/4" deep socket

TOOLS:

- [10mm Socket \(1\)](#)
- [1/4" Drive Ratchet \(1\)](#)

Step 1 — Remove the recoil starter bolts




- Before you begin, be sure that the engine is powered off and is cool to the touch.
- Use a 10 mm socket to remove the three 24 mm long bolts.

Step 2 — Remove the recoil starter assembly



- Remove the recoil starter assembly.

Step 3



- ⓘ If you are replacing the assembly with a **non-OEM part**, you may also have to replace the starter cap.
- Remove the 3/4" bolt with a deep socket.
 - This bolt can be very difficult to remove. Use the hook as a bracing point to keep the starter cap from rotating.

To reassemble your device, follow these instructions in reverse order.