




# Montgomery Ward GEN-39500 Antenna Replacement

Written By: Dustin Platt



---

## INTRODUCTION

The antenna receive an AM/FM radio signal. This guide will help you replace your antenna in case it is damaged.

---



### TOOLS:


- [Soldering Iron](#) (1)
  - [Phillips #2 Screwdriver](#) (1)
-

## Step 1 — Back Cover



- Remove the nine 35 mm Phillips screws securing the back cover of the case.



## Step 2



- Carefully remove the back cover.
- ⓘ Soldered wires connect electronics on the back cover to the internal electronics. Be careful not to break any connections.





### Step 3




- Unplug the black and yellow wires connecting the power supply unit to the rest of the electronics:
- ⓘ This is not necessarily required. This step is to allow the back cover more movement as you work on the inside of the unit.

### Step 4 — Antenna



- Unsolder the wire connecting the antenna to the radio.

## Step 5



- Tilt the back cover up and remove the two 7.5 mm Phillips screws holding the antenna in place.

## Step 6



- Remove the antenna.

To reassemble your device, follow these instructions in reverse order.