



Nokia 5165 Screen Replacement

Nokia 5165 Screen Replacement

Written By: Ethan Pikscher



 **TOOLS:**

- [T6 Torx Screwdriver \(1\)](#)

 **PARTS:**

- [Nokia 5165 Screen \(1\)](#)

Step 1 — Removing The Battery



- Remove the battery by pushing the button and sliding the battery out a bit then pulling it out

Step 2 — Removing The Front Cover




- Find the tab at the top of the phone and press down with your fingernail or the flat end of a spudger
- The top of the cover should pop out and then pull the top part out and the whole thing should come off

Step 3 — Removing The Screen



- Remove these screws
 - 4 T6 Torx Screws
- Lift up the white cover

Step 4



- Remove these screws
 - 2 T6 Torx screws
- Lift up the screen and number pad assembly
- Remove the blue separator and put it on the new screen

To reassemble your device, follow these instructions in reverse order.