




Nokia 8290 Vibrator Replacement

Use this guide to replace or repair your Nokia 8290's vibrator.

Written By: Parker Niebauer



INTRODUCTION

Installing a new vibration component is necessary when the vibrate mode on your phone is no longer functioning properly. Installation requires no prior knowledge of mobile phone vibrators.

TOOLS:


- [64 Bit Driver Kit \(1\)](#)
- [Tweezers \(1\)](#)

Step 1 — Front Cover



- Locate the small button on the top of the phone.
- Depress the button.
- With your other hand, pull the front cover away from the phone.



Step 2 — Vibrator



- Remove all six 5.3 mm long T6 screws.
- Remove the circuit board/faceplate sub-assembly from the back of the phone.

 Take care to place screws in a safe location.

Step 3



- After removing the circuit board/faceplate sub-assembly, locate the vibrator mechanism.
- Remove the vibrator mechanism with tweezers by simply pulling it up and away from the phone.

To reassemble your device, follow these instructions in reverse order.